



**COMMERCIAL VEHICLE AUCTIONS LTD**  
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate  
Doncaster  
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

# VEHICLE INSPECTION REPORT

**CV16XWG**

## Ford Transit 350 2.2 TDCI 155PS

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	Buyer To Apply

### Details

Reg. date	15/06/2016	Colour	WHITE	CAP Average	£2,325.00
Year	2016	VIN	WFOXXXTTGXGA15019	CAP Below	£1,675.00
Mileage	168,687 Miles Warranted	Body Style	Panel Van L2	Gearbox	MANUAL
Fuel Type	Diesel	MOT Due	14/06/2026	Gears	6
GVW	3500kg	CAP Clean	£2,850.00	Axle Combi	4x2

\*COLLECTED AS NON-RUNNER-ENGINE FAULT, WARNING LIGHT ON DASH\* 240v SOCKETS, SIDE LOAD DOOR, TOW BAR, ROOF RACK, E/MIRRORS, HEATED WINDSCREEN, SOCKET & USB IN CAB, V5 NEW KEEPER DOCUMENT REFERENCE NUMBER AVAILABLE FOR TAXATION PURPOSES

### Tyres






NSF
NSR
OSF
OSR
Spare

## Features

- Bluetooth connection
- Drivers airbag
- Park assist camera
- Passenger airbag
- Radio/CD
- Central locking
- Front electric windows
- Cloth seat trim


## Photos







## Condition Check



## Damage Photos



1: Dash Warning Lights  
Displayed  
No Action

2: Centre Console Front  
Holed  
Over 3mm



3: Carpets Front  
Holed  
Over 3mm

4: Seat Base Cover of  
Holed  
Over 3mm



5: Screen Front  
Chipped  
Over 10mm

6: Bonnet  
Chipped  
Multiple Chips



7: Bumper Front  
Scratched  
Over 100mm Thru Paint

8: Bumper Front Moulding  
Scratched (Painted)  
Over 25mm Thru Paint



9: Wing nsf  
Scratched  
Over 25mm Thru Paint

10: Door Mirror Assy nsf  
Broken  
Replace




11: Door Mirror Glass ns  
Missing  
Replace

12: Door nsf  
Scratched  
Over 25mm Thru Paint



13: Door Moulding nsf  
Scratched (Painted)  
UpTo 25mm Thru Paint

14: Qtr Panel nsr  
Scratched  
Over 25mm Thru Paint



15: Qtr Panel nsr  
Scratched  
Over 25mm Thru Paint



16: Qtr Panel nsr  
Dented  
Over 30mm



17: Qtr Panel nsr  
Scratched  
Over 25mm Thru Paint



18: Qtr Panel nsr  
Scratched  
Over 25mm Not Thru Paint



19: Bumper Rear  
Scratched  
Over 100mm Thru Paint

20: Door nsr  
Dented  
With Paint Damage



21: Door osr  
Dented  
Between 10mm + 30mm

22: Door osr  
Scratched  
Up To 25mm Thru Paint



23: Bumper Rear  
Scratched  
25 to 100mm Thru Paint

24: Qtr Panel osr  
Dented  
With Paint Damage



25: Qtr Panel osr  
Scratched  
Over 25mm Thru Paint

26: Qtr Panel osr  
Scratched  
Over 25mm Thru Paint



27: Qtr Panel osr  
Scratched  
Over 25mm Thru Paint

28: Door osf  
Chipped  
Multiple Chips



29: Door Mirror Glass os  
Broken  
Replace

30: Door Mirror Glass os  
Missing  
Replace



31: Bonnet  
Scratched  
Over 25mm Thru Paint

32: Bumper Front  
Scratched  
Over 100mm Thru Paint

## Interior

<b>Carpet Condition</b>	Average	<b>Upholstery Condition</b>	Average
<b>Seat Condition</b>	Average	<b>Odour</b>	-
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	Fault		
ABS light illuminated	Fault		